


NWDSF
0.0
PORSF
11.3.222

 POTENTIAL HAZARDOUS WASTE SITE SITE IDENTIFICATION		I. IDENTIFICATION	
		01 STATE	02 SITE NUMBER
II. SITE NAME AND LOCATION			
01 SITE NAME (Legal, common, or descriptive name of site) Nudelman and Son Inc.		02 STREET, ROUTE NO., OR SPECIFIC LOCATION IDENTIFIER 2707 N.W. Nela Street	
03 CITY Portland	04 STATE OR	05 ZIP CODE 97210	06 COUNTY Multnomah
		07 COUNTY CODE 051	08 CONG DIST
09 DIRECTIONS TO SITE (Starting from nearest public road) Take I-5 to I-205/Highway 30. Take Highway 30 to N.W. 31st Avenue, going North. N.W. Nela Street is just off 31st Avenue. Map in TSCA report.			
III. RESPONSIBLE PARTIES			
01 OWNER (If known) Standford J. Nudleman		02 STREET (Business, residential, mailing) 2707 N.W. Nela Street	
03 CITY Portland	04 STATE OR	05 ZIP CODE 97210	06 TELEPHONE NUMBER 603,226-4051
07 OPERATOR (If known and different from owner) Same as above		08 STREET (Business, residential, mailing)	
09 CITY	10 STATE	11 ZIP CODE	12 TELEPHONE NUMBER ()
13 TYPE OF OWNERSHIP (Check one) <input checked="" type="checkbox"/> A. PRIVATE <input type="checkbox"/> B. FEDERAL: _____ (Agency name) <input type="checkbox"/> C. STATE <input type="checkbox"/> D. COUNTY <input type="checkbox"/> E. MUNICIPAL <input type="checkbox"/> F. OTHER: _____ (Specify) <input type="checkbox"/> G. UNKNOWN			
IV. HOW IDENTIFIED			
01 DATE IDENTIFIED 8/10/88 MONTH DAY YEAR	02 IDENTIFIED BY (Check all that apply) <input checked="" type="checkbox"/> A. CITIZEN COMPLAINT <input type="checkbox"/> B. INDUSTRY <input type="checkbox"/> C. STATE/LOCAL GOVERNMENT <input type="checkbox"/> D. AERIAL RECONNAISSANCE <input type="checkbox"/> E. RCRA INSPECTION <input type="checkbox"/> F. SURFACE IMPOUNDMENT ASSESSMENT <input type="checkbox"/> G. OTHER EPA IDENTIFICATION <input type="checkbox"/> H. OTHER _____ (Specify)		
V. SITE CHARACTERIZATION			
01 TYPE OF SITE (Check all that apply) <input checked="" type="checkbox"/> A. STORAGE <input type="checkbox"/> B. TREATMENT <input checked="" type="checkbox"/> C. DISPOSAL <input checked="" type="checkbox"/> D. UNAUTHORIZED DUMPING <input type="checkbox"/> E. OTHER _____ (Specify)			
02 SUMMARY OF KNOWN PROBLEMS (Provide narrative description) The property (approx. 2 acres) was used for salvaging transformers and other devices for about 25 years. Oil spills are common on the property. TSCA inspection report is attached.			
03 SUMMARY OF ALLEGED OR POTENTIAL PROBLEMS (Provide narrative description) Potential soil and groundwater contamination with PCB containing oil.			
VI. INFORMATION AVAILABLE FROM			
01 CONTACT Ron Culver		02 OF (Agency/Organization) EPA - 000	
		03 TELEPHONE NUMBER 603,221-2676	
04 PREPARED BY Tom Robertson		05 AGENCY EPA	06 ORGANIZATION 000
		07 TELEPHONE NUMBER 603,294-7024	08 DATE 9/13/88 MONTH DAY YEAR